





## *Interface module assembly example*

**STEP 1**




1. Prepare component leads and insert into the desired positions.

**STEP 2**



2. Strip wire leads approximately 0.3". Insert stripped wire leads into the desired positions and tighten terminal block screws.

**STEP 3**



3. Slide interface module onto DIN rail. Plug cable assembly into interface module connector and secure cable hardware to interface module threaded inserts.