



Typical installation of an MD44FT field installable jack

Mini DIN 4 - S-Video Jack


Black Center 4
Black Shield 2



3 Yellow Center
1 Yellow Shield



Prepare coaxial lines.



Insert center conductors, shields and tighten set screws.



Secure cable with cable tie to connector.



Attach to faceplate and install.