


Tip***Accessories for the XP-FIT Field Termination Kit and Connectors***

When using the XP-FIT Field Termination Kit and the XPFIT field terminable LC or SC connectors, L-com recommends two additional accessories: A fiber launch cable and a fiber coupler. Having a launch cable will allow an installer to be sure each cable works by having a tested, known quantity cable readily available. A coupler will allow any newly created cable to be joined to the launch cable for testing purposes. The type of cable and coupler can vary based on your individual application as the mode of the cable and coupler must match for an accurate reading. The light source fiber checker included in the kit will work with any 2.5mm or 1.5mm connector including common connectors such as LC, SC, ST, and FC.




Light source fiber checker

+



Fiber optic coupler

+



Fiber optic launch cable